

Impact of 2016 Kumamoto Earthquakes on Nippon Gohsei (7th Report)

Our deepest sympathy goes out to those affected by the 2016 Kumamoto Earthquakes. We pray for the fast recovery of the affected areas as early as possible.

We would like to make our 7th report on the situation of Nippon Gohsei as of 9:00 a.m. on June 28.

Description

Situation of Kumamoto Plant

Our Kumamoto Plant has resumed operations in sequence from the production facilities that restoration work has been completed.

As of June 28, we forecast the following production resumption.

“OPL-Film”

The production facilities finished with restoration have resumed operation in sequence from June 21.

Our Ogaki Plant is substituting the production of some series of “OPL-Film”.

“Gohsenol” and “Gohsenx”

- 1) The production of “Gohsenx Z” has resumed from June 2.
- 2) The production of “Gohsenol EG” has resumed from June 2.
- 3) The production of “Gohsenx L-3266” will resume in the middle of July.

Other series of “Gohsenol” and “Gohsenx” will resume in September or later because the restoration of the facilities will take time.

Our Mizushima Plant is substituting the production of some series of “Gohsenol”.

We will continue doing our best for the restoration of the Plant, and keep you informed of any progress in the situation.