

Impact of 2016 Kumamoto Earthquakes on Nippon Gohsei (8th Report)

Our deepest sympathy goes out to those affected by the 2016 Kumamoto Earthquakes. We pray for the fast recovery of the affected areas as early as possible.

We would like to make our 8th report on the situation of Nippon Gohsei as of 3:00 p.m. on July 28.

Description

Situation of Kumamoto Plant

Our Kumamoto Plant has resumed operations in sequence from the production facilities that restoration work has been completed.

As of July 28, we forecast the following production resumption.

“OPL-Film”

All four production facilities have resumed operation.

“Gohsenol” and “Gohsenx”

- 1) The production of “Gohsenx Z” has resumed from June 2.
- 2) The production of “Gohsenol EG” has resumed from June 2.
- 3) The production of “Gohsenx L-3266” has resumed from July 13.

Other series of “Gohsenol” and “Gohsenx” will resume in September because the restoration of the facilities will take time.

Our Mizushima Plant is substituting the production of some series of “Gohsenol”.

We will continue doing our best for the restoration of the Plant, and keep you informed of any progress in the situation.